United States Environmental Protection Agency EPA New England One Congress Street, Suite 1100 Boston, MA 02114-2023

September 14, 2004

To: J. Kilborn, EPA

H. Inglis, EPA

R. Howell, EPA

D. Moore, USACE

K.C. Mitkevicius, USACE

S. Steenstrup, MA DEP (2 copies)

S. Peterson, CT DEP

A. Silfer, GE

J. Novotny, GE

J.R. Bieke, Esquire, Shea & Gardner

S. Messur, BBL

D. Young, MA EOEA

K. Munney, US Fish and Wildlife

R. Cataldo, ENSR

R. Nasman, The Berkshire Gas Company

Mayor Ruberto, City of Pittsfield

Commissioner of Public Works and Utilities, City of Pittsfield

Public Information Repositories

RE: August 2004 Monthly Report

1.5 Mile Reach Removal Action

GE-Pittsfield/Housatonic River Site

Enclosed please find the August 2004 Monthly Report for the 1.5 Mile Reach Removal Action. In accordance with the Consent Decree for the GE-Pittsfield/Housatonic River Site, the United States Environmental Protection Agency (EPA) is performing the 1.5 Mile Reach Removal Action, with General Electric funding a portion of the project through a cost sharing formula.

The EPA has entered into an agreement with the United States Army Corps of Engineers (USACE) to assist in the design and construction of the Removal Action. The USACE subsequently awarded a design-construct contract to Weston Solutions, Inc. (Weston). Weston, with several subcontractors, will be performing the design and construction activities for the 1.5 Mile Reach Removal Action.

If you have any questions, please contact me at (413) 236-0969. Sincerely,

Dean Tagliaferro

1.5 Mile Reach Removal Action Project Manager

1. Overview

During August 2004, the Environmental Protection Agency (EPA), the United States Army Corps of Engineers (USACE), the USACE's contractor, Weston Solutions, Inc., and Weston's subcontractors continued remediation activities on the 1.5 Mile Reach Removal Action. The primary work included completing backfilling of Cells 16E and 17E. Excavation and riverbed power washing activities in Cells 18E and 19E were completed. Backfilling activities in Cells 18E and 19E were also completed. Excavation activities were initiated in Cell 18W. In addition, transfer of non-TSCA materials from the stockpile management areas to the GE On Plant Consolidation Areas (OPCAs) was performed. Also, transfer of non-TSCA and NAPL-impacted materials from the stockpile management areas to approved off-site facilities continued.

2. Chronological description of tasks performed

Refer to Figure 1 for an orientation of the excavation cells and their respective locations.

By the end of July 2004, excavation activities in Cell 17E were completed and backfilling activities in Cell 17E were ongoing. During the first week of August backfilling activities in Cell 17E continued. Due to the presence of bedrock within the entire riverbed of Cell 17E, excavation depths varied. Therefore, various backfill configurations were developed to meet the design requirements. Twelve-inch riprap was placed in low lying areas and depressions in the bedrock to bring the excavated surface up to grade. Areas of the riverbed where the excavation depth was greater than 3 feet were backfilled with a layer of common fill, filter material, and 12-inch riprap. Areas of the riverbed where bedrock was encountered at very shallow depths were either backfilled with filter material or were left with the bedrock exposed. The riverbank was backfilled with a six-inch layer of common fill, a six inch layer of filter material and a twenty four-inch layer of 18-inch riprap up to the 1.5 year flood elevation, which ranges between 969.5 feet to 970.5 feet. The riverbank above those elevations was backfilled with common fill and a six-inch layer of top soil.

Riverbank backfilling activities also continued in Cell 16E to the 1.5 year flood elevation. Common fill was installed in twelve inch horizontal lifts and compacted to meet the 95% compaction requirement. Then, a minimum six-inch layer of topsoil, erosion control blankets and herbaceous seed mix were installed.

Also by the end of July 2004, activities associated with preparation of Cell 18E for excavation activities were completed. This included the dewatering and installation of sumps and trenches in Cell 18E. During the first week in August, preparation of Cell 19E for excavation was completed. A temporary dam was built between Cell 18E and 19E to separate the excavation zones between the cells, to better facilitate dewatering activities and to ease the storm water management in the cells. Construction of a load out area on the Cell 18W riverbank was

completed. First, riverbank excavation activities were completed in Cells 18E and 19E. The excavated riverbank material from Cells 18E and 19E was placed into an Articulated Dump Truck (ADT) which transported and dumped the material into a roll-off box located in the river channel in Cell 18E. The material was then loaded into dump trucks by a long stick excavator located on the load out area on the riverbank of Cell 18W and hauled to the appropriate stockpile management area. The non-TSCA riverbank material pre-characterized for offsite disposal was transported to Area 64D; due to the large quantity of non-TSCA riverbank material precharacterized for offsite disposal generated during the excavation of Cells 18E and 19E riverbanks, the Area 64D stockpile management area was filled to capacity. Therefore, the Cell 18E and 19E non-TSCA pre-characterized material was transported to the Area 64B stockpile management area. The non-TSCA riverbank material uncharacterized for off-site disposal was transported to Building 65 stockpile management area (then relocated to Area 64C on 8/12/04); and the TSCA riverbank material was transported to Area 64A stockpile management area. (See Table 1 for quantities of material generated in the month of August 2004 and Table 2 for quantities of material generated to date). With a flood warning forecasted for Berkshire County, erosion controls were installed on the lower sections of the excavated riverbanks. This consisted of covering the excavated riverbanks with reinforced poly and filter stone.

Once the riverbank excavation in Cell 18E and 19E was completed, the load out roll-off box was relocated to the Cell 20 river channel. Activities associated with preparation of a load out area on Parcel I7-21-3 (Cell 20W riverbank) were completed. The long stick excavator was relocated to the load out area on Parcel I7-21-3. The dewatering of Cells 18E and 19E was completed and the riverbed excavation of Cells 18E and 19E was initiated. First, the cobble material was excavated from Cell 18E and 19E river bottom. The excavated cobble material was placed into an ADT which transported and dumped the material into a roll-off box located in the river channel in Cell 20. The material was then loaded into dump trucks by a long stick excavator located on the load out area on Parcel I7-21-3 and hauled to Area 64E stockpile management area. During the excavation of the cobble material, NAPL was observed in both Cell 18E and 19E in the riverbed and at the toe of the riverbank. The NAPL material was left undisturbed during the removal of cobble and will be excavated once the cobble material is removed. The free flowing NAPL was controlled and removed with a vacuum truck and subsequently transferred to the water treatment system modutank.

Surveying activities continued in Cells 16 and 17. Final restoration verification surveying activities were initiated above the 1.5 year flood elevation in Cells 16E and 17E. The surveyors also monitored the excavation activities in Cells 18E and 19E to ensure appropriate design excavation depths were achieved. Once the riverbanks in Cell 18E and 19E were excavated, the final excavation survey was initiated on the riverbanks.

Other activities during the first week of August included the installation of a riprap swale on the riverbank in 17E. The swales were necessary to prevent riverbank erosion caused by storm water coming from High Street. A steel cap was installed on the NAPL interceptor system in the Cell 17E NAPL hole.

Work associated with removing tree and brush debris and cleaning up the riverbanks beyond the limit of excavation in Cells 16W and 17W was completed. The tree and brush debris was moved

to the staging area on the Lyman Street Parking lot. All the tree debris and brush chipping was completed.

During the second week in August, all backfilling below and above the 1.5 year flood elevation, which ranges between 969.5 feet to 970.5 feet of Cells 16E and 17E was completed in accordance with the backfill configurations described above.

Also during the second week of August, the riverbed excavation activities continued in Cell 18E and 19E. The excavation of NAPL-impacted material was completed in Cell 18E and the upstream end of Cell 19E. The NAPL-impacted material was encountered throughout Cell 18E riverbed and at the upstream end of Cell 19E riverbed. NAPL-impacted material was also encountered at the toe of the riverbank in the entire length of Cell 18E. The NAPL-impacted material extended about eight feet into the riverbank at the upstream end of the cell and tapered off gradually towards the downstream end of the cell ranging from one foot to three feet in depth. The Cell 18E and 19E NAPL-impacted material was transported to the Building 68 stockpile management area. In some areas in Cell 19E, the NAPL material overlapped into the TSCA areas. This material was excavated and transported to the Building 65 stockpile management area (then on 8/31/04 this material was relocated to Building 68 into a separate pile from the non-TSCA NAPL). All of the water and the free flowing NAPL from the excavation areas were diverted to the water treatment system.

Bedrock was encountered in the entire river bottom of Cell 18E and the upstream end of 19E. In addition to the standard excavation equipment, a small track excavator was used to access and remove the NAPL-impacted material and sediment from the areas of the river bottom where crevasses and depressions in the weathered bedrock were numerous. In most areas, there was less than 2-feet of sediment above the bedrock. Most of the bedrock within the riverbed in Cell 18E and upstream end of Cell 19E was stained with NAPL. The high pressure power washing of bedrock to remove any loose sediment and NAPL staining was initiated in Cell 18E and upstream end of Cell 19E. High pressure power washing of bedrock was supplemented with a vacuum truck to remove any residual sediment and NAPL from the bedrock. All water generated during the power washing was diverted to the water treatment system. All the residual sediment material was collected into roll-off boxes located in the riverbed and subsequently transferred to the water treatment system modutank.

The bedrock power washing and the vacuuming activities in Cell 18E and upstream end of Cell 19E had to stop on 8/12/03 due to heavy rains and heavy storm water discharge from the Elm Street storm water outfall that caused flooding in Cells 18E and 19E. Bin blocks were installed in the river bottom of Cell 14W at the Elm Street storm water outfall to protect the ACB from storm water erosion. Also, with the forecast of a tropical storm heading for the northeast for the weekend, additional erosion control measures were installed on the lower sections of the excavated river banks in Cells 18E and 19E. The riverbanks were covered with reinforced poly which was anchored down by sand bags at the top of the slope and riprap at the toe of the bank.

During the third week in August, Cells 18E and 19E were flooded from the weekend rain. On Monday, dewatering activities in Cell 18E and 19E were initiated. The river channel was dewatered by pumping the water down to six inches in depth downstream of the excavation areas. The water below six inches in depth was diverted to the water treatment system. Once the

dewatering was completed, the high pressure bedrock power washing and bedrock vacuuming was re-started. Since some of the bedrock in excavated areas in Cell 18E was not power washed before the flooding occurred and the flooding deposited a significant amount of material on the already washed bedrock, it was necessary to re-wash the entire riverbed of Cell 18E. All water generated during the power washing was diverted to the water treatment system. The residual sediment from the bedrock was removed by the vacuum truck. The more significant amounts of sediment were removed by the small track excavator. All the residual sediment material was collected into roll-off boxes located in the riverbed and subsequently transferred to the water treatment system modutank.

With the hurricane season under way it was decided that to minimize the potential for cross contamination and to advance the completion of Cell 18E, the riverbed was to be inspected and approved for backfilling as the power washing progressed downstream. Therefore the upstream sections of Cell 18E would be backfilled while the downstream portion of Cell 18E was power washed. As the riverbed power washing progressed downstream of Cell 18E, the excavation verification survey was completed, backfill grade stakes were installed and the riverbed and riverbank backfilling activities were initiated in the upstream end of Cell 18E. All visible NAPL was successfully removed from the riverbed and the riverbanks of Cell 18E. No NAPL containment measures were necessary in Cell 18E. A sacrificial layer of filter fabric and common fill were installed in the riverbed along the Cell 18E and Cell 18W border to create a barrier between the clean backfill that is to be installed and the contaminated sediment in Cell 18W.

Due to the presence of bedrock within the entire riverbed of Cell 18E, excavation depths varied. Therefore, various backfill configurations were developed to meet the design requirements. Twelve-inch riprap was placed in low lying areas and depressions in the bedrock to bring the excavated surface up to grade. Areas of the riverbed where the excavation depth was greater than 3 feet were backfilled with a layer of common fill, filter material, and 12-inch riprap. Areas of the riverbed where the excavation depth was less than 2.5 feet were backfilled with a layer of filter material and 12-inch riprap. Areas of the riverbed where bedrock was encountered at very shallow depths were either backfilled with filter material or were left with the bedrock exposed. The riverbank was backfilled with a six-inch layer of common fill, a six inch layer of filter material and a twenty four-inch layer of 18-inch riprap up to the 1.5 year flood elevation, which ranges between 969.5 feet to 970.5 feet. The riverbank above those elevations was backfilled with common fill and a six-inch layer of top soil.

Once riverbed power washing was completed in Cell 18E, power washing and vacuuming activities were initiated in the upstream end of Cell 19E. In addition, non-TSCA sediment material was excavated from low spots in the river bottom in Cell 19E. The excavated material was loaded into an ADT which transported and dumped the material into a roll-off box located in the river channel in Cell 20. The material was then loaded into dump trucks by a long stick excavator located on the load out area on Parcel I7-21-3 and hauled to Area 64C stockpile management area. As in Cell 18E, it was decided that the upstream sections of Cell 19E would be backfilled while the downstream portion of Cell 18E was power washed. Therefore as soon as a significant section of the riverbed was power washed, the excavation verification survey was completed. A protective filter fabric and common fill barrier was built between Cells 19E and

19W and riverbed backfill activities were initiated. Backfilling activities in Cell 19E was performed in accordance with the backfill configurations described above for Cell 18E.

Fusion welding of flange adapters onto the remaining two 300-foot sections of 54-inch HDPE river diversion pipe was completed. The two pipe pieces will eventually be connected to the e two 2,750-foot pieces of pipe already in use. In the future the new two 300-foot pipe additions will extend the gravity bypass system beyond the Dawes Avenue Bridge and will allow the Phase 2 remediation work to extend down to the Dawes Avenue Bridge.

Other activities during the third week in August included power washing of the large boulders excavated from Cell 18E and 19E. The large boulders will be re-used as aquatic enhancement boulders in future riverbed restoration activities.

Due to heavy rains and high water flows on August 21, 2004 the stop logs were removed from the temporary dam to an elevation of 973 feet and the river channel downstream of the dam was flooded, subsequently flooding Cells 18 and 19. The next day the water levels started to recede and the stop logs were re-installed into the dam to elevation 978 and the dewatering pumps were started.

During the fourth week in August, the dewatering activities were completed in Cells 18E and 19E. A temporary sand bag dam was re-built at the downstream end of Cell 19E to aid with the dewatering process. Once dewatering was completed, Cell 19E bedrock power washing, vacuuming and removal of non-TSCA sediment from the low spots in the riverbed were completed. The excavated non-TSCA sediment material from low spots was transported to Area 64C stockpile management area. In two locations in the riverbed, a three-foot layer of sediment was excavated, but bedrock was not reached. However, a dense till material was encountered. EPA directed that three confirmation samples be collected from the dense till material and analyzed for PCBs. The PCB results were all less than the 1 ppm clean up goal for sediments. Therefore, the excavation in these two locations was terminated. One small area of the downstream part of Cell 19E river bottom adjacent to Cell 20E still required excavation. The non-TSCA cobble material from the area was excavated and transported to Area 64E stockpile management area. This completed the riverbed excavation in Cell 19E.

Survey activities in Cell 19E continued. The excavation verification survey was completed and the backfill grade stakes were installed. The riverbank excavation verification survey in Cell 19E revealed that additional riverbank soil needed to be excavated to meet the required design depth. Approximately 20cy of pre-characterized for offsite disposal riverbank soil was excavated and transported to the Area 64D stockpile management area. This completed the riverbank excavation activities in Cell 19E. All visible NAPL was successfully removed from the riverbanks of Cell 19E. No NAPL containment measures were necessary in Cell 19E.

River bottom backfill activities in Cell 19E were completed and the riverbank backfilling was initiated. The riverbed was backfilled in the following configurations: twelve inch riprap was placed in low lying areas and depressions in the bedrock to bring the excavated surface up to grade; areas of the riverbed where the excavation depth was greater than 3 feet were backfilled with a layer of common fill, filter material, and 12-inch riprap; which includes the areas that

were excavated to dense till and sampled for PCBs; areas of the riverbed where the excavation depth was less than 2.5 feet were backfilled with a layer of filter material and 12-inch riprap; areas of the riverbed where bedrock was encountered at very shallow depths were either backfilled with filter material or were left with the bedrock exposed. The riverbank was backfilled with a six-inch layer of common fill, a six inch layer of filter material and a twenty four-inch layer of 18-inch riprap up to the 1.5 year flood elevation, which ranges between 969.5 feet to 970.5 feet.

Also, during the fourth week in August, Cell 18E riverbank backfilling activities above the 1.5 year flood elevation continued. Common fill was installed in twelve inch horizontal lifts and compacted to meet the 95% compaction requirement. Then, a minimum six-inch layer of topsoil, erosion control blankets and herbaceous seed mix were installed. Silt fencing was installed along the top of the riverbank in Cell 18E as an erosion control measure. Once the silt fencing was installed all backfill activities in Cell 18E were concluded and the survey contractor completed the final restoration survey in Cell 18E. The riverbank above elevations the 1.5 year flood elevation in Cell 19E was backfilled with common fill. A portion of Cell 19E riverbank with slopes steeper than 2H:1V requires cellular geoweb for riverbank stability purposes. Therefore topsoil, erosion control blankets and herbaceous seed mix will be placed in Cell 19E once the geoweb is installed.

An application of herbicides to control the invasive plants in Phase 1, the Transition Phase and Phase 2 was performed. Also, the final coat of paving was installed on the parking lot of Parcel I8-23-6 in the area affected by the 24-inch storm water outfall repairs completed in April 2004.

During the last week in August activities associated with 54-inch HDPE pipe relocation were completed. All construction equipment and supplies were removed from the riverbed, stop logs were removed from the temporary dam and the river channel downstream of the temporary dam was flooded with enough water to float the pipe across the river channel. The two 54-inch HDPE pipes were relocated from the west side to the east side of the river channel. Once the relocation was completed the pipes were then reconnected to the pipe restraint system. The steel plate energy dissipater at the 54-inch pipe outfall located approximately one hundred feet upstream of the Dawes Avenue Bridge was relocated from the west side to the east side of the river channel. Additional bin blocks were placed at the toe of the riverbank on the east side of the river channel to protect the riverbank from erosion from the 54-inch pipe outfall.

Once the 54-inch pipe was relocated, dewatering activates in Cell 18W were completed, and excavation activities in Cell 18W were initiated. A majority of Cell 18W and all of Cell 19W lower riverbank was previously remediated by GE in mid 1990's. Part of the GE riverbank restoration included the installation of reno mattresses and gabion baskets. Coconut logs were installed above the gabion baskets. The reno mattresses at the base of the gabion wall were being undermined compromising the structural stability of the reno mattresses/gabion baskets and therefore the riverbank itself. It was unknown how riverbed excavation activities in Cells 18W and 19W adjacent to the gabion basket wall would affect the stability of the reno mattresses/gabion baskets. To ensure long-term stability of the riverbank EPA decided it was prudent to remove the reno mattresses, the gabion baskets and the coconut logs. In order to achieve the 1.5 Mile riverbank clean up levels, additional riverbank soil would have to be removed to allow for a placement of a three foot layer of backfill. The lower riverbank will be

backfilled with a six-inch layer of common fill, a six inch layer of filter material and a twenty four-inch layer of 18-inch riprap. EPA and GE agreed that to account for the disposal of the excavated reno mattresses, the gabion baskets and the coconut logs, EPA will be allotted an additional 750cy of space in GE OPCAs. The gabion basket rock was excavated and transported to Area 64B stockpile management area and the underlying riverbank material uncharacterized for offsite disposal was transported to Area 64C.

During the month of August, the water treatment system treated water from Cells 18 and 19. Sampling of the water treatment system for parameters included in the NPDES exclusion permit was performed on August 18, 2004. An additional two samples were collected from the water treatment system, one sample between the modutank and the oil/water separator and the other between the sand and carbon filter. Also, due to the presence of NAPL in Cells 18 and 19, the analytical parameters for the water treatment system sampling were expanded to include volatiles and semi-volatiles. Air monitoring for particulate matter (PM10 sampling) and surface water turbidity monitoring were performed on a daily basis during the month of August. Surface water sampling for total suspended solids (TSS) and PCBs was performed on August 04, 2004 and August 19, 2004. The monthly PCB air-monitoring event was performed on August 12, 2004. Three eight-point composite off-site disposal characterization samples were collected from NAPL-impacted material from Cells 18E and 19E (currently stockpiled in Building 68) on August 16, 2004. Since the NAPL-impacted material from Cell 19E that overlapped into the TSCA areas resulted with a non-TSCA PCB result post excavation, two more eight-point composite off-site disposal characterization samples were collected from the material on August 26, 2004 for PCB analysis only. Sampling of topsoil for chemical parameters was performed on August 11, 2004. Three PCB excavation confirmation samples were collected in the riverbed of Cell 19E on August 24, 2004.

Geotechnical samples were collected for 18-inch riprap and topsoil. The results of the geotechnical testing are not included in the monthly report but are contained in other submittals and are available upon request.

The transfer of non-TSCA cobble materials from the Area 64E stockpile management area to the Hill 78 OPCA was performed on August 11, 2004, August 12, 2004 and August 31, 2004. (See Table 3 for a summary of material transported to the OPCAs during the month of August 2004 and Table 4 for a summary of material transported to the OPCAs for the project through August 2004.)

Also, Cells 16 and 17 non-TSCA post excavation characterized riverbank and riverbed materials from the Area 64C stockpile management area; Cells 16 and 17 NAPL impacted non-TSCA post excavation characterized riverbank and riverbed materials from the Building 68, Building 63 and Building 65 stockpile management areas; and Cells 18 and 19 pre-characterized non-TSCA riverbank materials from Area 64D and Area 64B stockpile management areas were transported to the Waste Management of New Hampshire-TREE, Rochester, NH from August 04, 2004 to August 19, 2004. (See Table 5 for a summary of material transported to the Waste Management of New Hampshire-TREE, Rochester, NH during the month of August 2004.)

Stockpile management area activities continued throughout the month of August. Daily inspections, operation, and maintenance activities were performed within Buildings 63, 65, Area

64 (the outside stockpile area) and Building 68. Cleaning of the storm drain covers and replacement of fabric and hay bails around the storm drains within stockpile management areas on GE property was completed. A vacuum truck was utilized to collect the water runoff from the stockpiled material. The water was then transported to the water treatment system. Dust control procedures continued for access roads, parking areas, and material storage areas.

Traffic control was conducted on Lyman Street, High Street, Deming Street and Elm Street during the month of August.

3. Sampling/test results received

Table 6 contains a summary of the PCB samples collected for the water treatment system sampling program on August 18, 2004, and the non-PCB data associated with the water treatment system sampling on August 18, 2004 is presented in Table 6a. The results of the daily particulate air monitoring program are summarized in Table 7. Table 8 is a summary of daily turbidity monitoring results. Results for PCB and TSS samples and water column monitoring data collected on July 22, 2004, August 04, 2004 and August 19, 2004 are presented in Table 9. Analytical results for the PCB air sampling conducted on August 12, 2004 are provided in Table 10. Table 11 presents common fill sample results collected on July 22, 2004 and topsoil sample results collected on August 11, 2004. Post-excavation characterization sample results for NAPL-impacted material (Building 68 stockpile management area) collected on August 16, 2004 and August 26, 2004 are summarized in Table 12. Table 13 presents PCB data associated with excavation confirmation samples collected in Cell 19E riverbed on August 24, 2004.

4. Diagrams associated with the tasks performed

Figure 1 is a map of Phase 1, the Transition Phase and Phase 2 and includes the layout of all excavation cells, temporary dam, water monitoring locations, air sampling locations, access road locations, excavation load out locations, staging area locations, fence line location, the water treatment system pad location, and the utility trench location.

5. Reports received and prepared

Vibration monitoring activities were not performed during the month of August.

6. Photo documentation of activities performed

See attached photos.

7. Brief description of work to be performed in September 2004

- Complete excavation activities in Cells 18W and 19W.
- Complete backfill activities in Cells 19E, 18W and 19W.
- Relocate and extend the 54-inch river diversion pipe below the Dawes Avenue Bridge.
- Initiate excavation activities in Cell 20E.
- Complete conditions and settlement monitoring activities on selected structures for Phase 3A.
- Continue stockpile management activities at Buildings 63, 65, 68 and Area 64 (outside contaminated material stockpile area).
- Continue transfer the non-TSCA materials from the stockpile management areas to approved off-site facilities.
- Continue to transfer TSCA and non-TSCA cobble material to the OPCAs.
- Continue daily air and turbidity monitoring.
- Continue PCB air sampling (once a month), water column sampling (twice a month), water treatment system sampling (once a month) and backfill material sampling (as needed).

8. Attachments to this report

- Table 1. Quantity of Bank and Sediment Material Excavated during the Month of August
- Table 2. Quantity of Bank and Sediment Material Excavated to Date
- Table 3. Quantity of Material Transferred to OPCAs during the Month of August
- Table 4. Quantity of Material Transferred to OPCAs to Date

- Table 5. Quantity of non-TSCA Material Transferred to Waste Management of New Hampshire TREE in Rochester, NH during the Month of August
- Table 6. NPDES PCB Sampling Results for Water Treatment System
- Table 6a. NPDES non- PCB Sampling Results for Water Treatment System
- Table 7. Daily Air Monitoring Results
- Table 8. Daily Water Column Turbidity Monitoring Results
- Table 9. Summary of Turbidity, PCB, and TSS Water Column Monitoring Results
- Table 10. PCB Air Sampling Results
- Table 11. Backfill Material Testing Results
- Table 12. Cell 18E/19E NAPL-Impacted Material Characterization Analytical Results
- Table 13. Cell 19E Excavation Confirmation Analytical Results
- Figure 1- 1.5 Mile Removal Action Site Map

Photodocumentation

Table 1 - Quantity of Bank and Sediment Material Generated During the Month of August August 2004 Monthly Report

GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

(Results are reported in cubic yards)

| | | Approximate Quantity of Excavated Bank ar Sediment Material | | |
|------------------|---|--|------|---------------|
| Date | Location | non-TSCA | TSCA | NAPL impacted |
| Bank Soil and Se | diment | | | |
| 8/2/2004 | Cell 18E&19E | 400 | 40 | 0 |
| 8/3/2004 | Cell 18E&19E | 590 | 0 | 0 |
| 8/4/2004 | Cell 18E&19E | 200 | 0 | 0 |
| 8/5/2004 | Cell 18E | 190 | 0 | 0 |
| 8/6/2004 | Cell 18E&19E | 420 | 0 | 0 |
| 8/9/2004 | Cell 18E&19E | 0 | 0 | 500 |
| 8/12/2004 | Cell 18E | 0 | 0 | 60 |
| 8/18/2004 | Cell 19E | 40 | 0 | 0 |
| 8/24/2004 | Cell 19E | 70 | 0 | 0 |
| 8/26/2004 | Cell 19E | 120 | 0 | 0 |
| 8/30/2004 | Cell 18W | 10 | 0 | 0 |
| 8/31/2004 | Cell 18W | 170 | 0 | 0 |
| | Monthly total from bank soil and sediment | 2,210 | 40 | 560 |

Note:

All quantities are in compacted or "in-place" cubic yards. All loads are estimated at 10cy per truck.

Table 2 - Quantity of Bank and Sediment Material Excavated to Date August 2004 Monthly Report

GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

(Results are reported in cubic yards)

| | | Approximate Quantity of Bank and Sediment Material Excavated to Date | | | | |
|----------------------|--------------------|--|-------|-------|--------|--|
| Date | Location | non-TSCA TSCA NAPL impacted Total | | | | |
| 09/26/02 to 10/02/02 | Cell 1A | 101 | 0 | 53 | 154 | |
| 10/02/02 to 10/04/02 | Cell 1B | 60 | 0 | 110 | 170 | |
| 10/18/02 to 10/29/02 | Cell 2 | 874 | 175 | 0 | 1,049 | |
| 11/11/02 to 11/15/02 | Cell 3 | 183 | 0 | 200 | 383 | |
| 11/18/02 to 11/25/02 | Cell 4 | 2,283 | 198 | 0 | 2,481 | |
| 12/03/02 to 12/10/02 | Cell 5 | 1,629 | 369 | 0 | 1,998 | |
| 01/07/03 to 01/15/03 | Cell 6 | 832 | 658 | 0 | 1,490 | |
| 01/10/03 to 01/29/03 | Cell 6A | 2,611 | 68 | 0 | 2,679 | |
| 02/03/03 to 02/10/03 | Cell 7&7A | 1,114 | 636 | 0 | 1,750 | |
| 02/20/03 to 02/24/03 | Cell 5A | 899 | 0 | 0 | 899 | |
| 02/25/03 to 03/07/03 | Cell 8&8A | 1,245 | 90 | 0 | 1,335 | |
| 03/14/03 to 03/18/03 | Cell 9 | 603 | 307 | 0 | 910 | |
| 03/27/03 to 04/07/03 | Cell 10&10A | 1,730 | 133 | 0 | 1,863 | |
| 04/14/03 to 04/16/03 | Cell 12 | 668 | 1,354 | 0 | 2,022 | |
| 04/30/03 to 05/09/03 | Cell 11 | 1,713 | 341 | 10 | 2,064 | |
| 05/27/03 to 06/12/03 | Cell 11A | 957 | 166 | 462 | 1,585 | |
| 06/25/03 to 07/18/03 | Cell 12A | 1,656 | 805 | 656 | 3,117 | |
| 09/04/03 to 10/22/03 | Cell 13 | 3,580 | 298 | 1,129 | 5,007 | |
| 01/08/04 to 03/24/04 | Cell 14&15 | 4,462 | 288 | 257 | 5,007 | |
| 5/25/04 to 07/30/04 | Cell 16&17 | 4,392 | 820 | 3,191 | 8,403 | |
| 8/02/04 to 08/31/05 | Cell 18E,19E&18W * | 2,210 | 40 | 560 | 2,810 | |
| | Total | 33,802 | 6,746 | 6,628 | 47,176 | |

Note:

All quantities determined by pre- and post- excavation surveying.

^{*} Cell 18E,19E&18W Quantities estimated based on truck counts at 10cy/truck

Table 3 - Quantity of Material Transferred to OPCAs During the Month of August August 2004 Monthly Report

GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

(Results are reported in cubic yards)

| | | Approximate Quantity T | ransported to OPCAs |
|---------------------|-----------------|------------------------|---------------------|
| Date | # of truckloads | Hill 78 (non-TSCA) | Bldg. 71 (TSCA) |
| Bank Soil and Sedin | nent | | |
| 8/11/2004 | 41 | 451 | 0 |
| 8/12/2004 | 10 | 110 | 0 |
| 8/31/2004 | 44 | 484 | 0 |
| Monthly totals | 95 | 1,045 | 0 |

Note:

All quantities are in compacted or "in-place" cubic yards.

(1) Estimated at 11 cy per truck

Table 4 - Quantity of Material Transferred to OPCAs to Date August 2004 Monthly Report

GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

(Results are reported in cubic yards)

| | | Approximate Quant | • |
|------------------------|--|--------------------|-----------------|
| Date | Location | Hill 78 (non-TSCA) | Bldg. 71 (TSCA) |
| Site Preparation Activ | ities | | |
| 09/11/02 | Building 65 Stockpile Management Area | 225 | |
| Bank Soil and Sedime | nt | | |
| 12/05/02 to 12/19/02 | Stockpile Management Area/Excavation Cells | 4,718 (1) | 910 (1) |
| 02/11/03 to 02/28/03 | Stockpile Management Area/Excavation Cells | 5,137 (2) | 539 (2) |
| 03/03/03 to 03/14/03 | Stockpile Management Area/Excavation Cells | 1,749 (2) | 1,353 (2) |
| 04/07/03 to 04/18/03 | Stockpile Management Area/Excavation Cells | 2,710 (3) | 1,698 (3) |
| 04/07/03 to 04/18/03 | Stockpile Management Area/Cleanup Material | 370 (3) | 40 (3) |
| 05/12/03 to 05/14/03 | Stockpile Management Area/Excavation Cells | 1,826 (3) | 0 |
| 05/12/03 to 05/14/03 | Stockpile Management Area/Cleanup Material | 220 (3) | 0 |
| 06/11/03 to 06/12/03 | Stockpile Management Area/Excavation Cells | 0 | 704 (3) |
| 06/16/03 to 06/17/03 | Stockpile Management Area/Excavation Cells | 712 (3) | 0 |
| 06/16/03 to 06/17/03 | Stockpile Management Area/Cleanup Material | 146 (3) | 0 |
| 07/07/03 to 07/11/03 | Stockpile Management Area/Excavation Cells | 1,188 (3) | 748 (3) |
| 09/15/03 to 09/30/03 | Stockpile Management Area/Excavation Cells | 2,090 (3) | 308 (3) |
| 10/28/03 to 10/30/03 | Stockpile Management Area/Excavation Cells | 1,623 (3) | 33 (3) |
| 10/28/03 to 10/30/03 | Stockpile Management Area/Cleanup Material | 181 (3) | 0 |
| 11/18/03 | Demolition Debris from Parcels I8-10-2 and I8-10-3 | 200 (4) | 0 |
| 1/12/04 | Stockpile Management Area/Excavation Cells | 77 (3) | 0 |
| 04/28/04 to 4/30/04 | Stockpile Management Area | 0 | 825 (3) |
| | Stockpile Management Area/Excavation Cells/Outfall | | |
| 05/12/04 to 05/27/04 | Repair on Parcel I8-23-6 | 1,518 (3) | 484 (3) |
| 06/03/04 to 06/22/04 | Stockpile Management Area | 0 | 528 (3) |
| 07/06/04 to 07/16/05 | Stockpile Management Area | 396 (3) | 836 (3) |
| 08/11/04 to 08/31/04 | Stockpile Management Area | 1,045 (3) | 0 |
| | | | |
| | Project Totals | 26,131 | 9,00 |

Pursuant to the Consent Decree, EPA is allowed to dispose of up to 50,00cy of material into GE OPCAs. Pursuant to August 2004 agreement between EPA and GE, EPA is allowed to dispose an additional 750cy of material into the GE OPCAs to account for a portion of the volume of material generated as part of the removal of the gabion baskets and reno mattresses along Deming Street. Notes:

All quantities are in compacted or "in-place" cubic yards.

- (1) Estimated at 14cy per truck, loaded with excavator.
- (2) Estimated at 11cy per truck due to loading out frozen material.
- (3) Estimated at 11cy per truck, loaded with front end loader.
- (4) Estimated at 8cy per truck

Table 5 - Quantity of non-TSCA Material Transported to Waste Management of New Hampshire-TREE, Rochester, N.H. During the Month of August August 2004 Monthly Report

GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

(Results are reported in tons)

| Date Shipped | Doc. Number | Stockpile Area | Net Weight (Tons) (1) |
|--------------|-------------|-----------------------------|-----------------------|
| 08/04/04 | 0401WMNH | Cell 16/17 Area 64C | 31.55 |
| 08/04/04 | 0402WMNH | Cell 16/17 Area 64C | 31.43 |
| 08/04/04 | 0403WMNH | Cell 16/17 Area 64C | 25.71 |
| 08/04/04 | 0404WMNH | Cell 16/17 Area 64C | 28.94 |
| 08/04/04 | 0405WMNH | Cell 16/17 Area 64C | 31.77 |
| 08/04/04 | 0406WMNH | Cell 16/17 Area 64C | 31.00 |
| 08/04/04 | 0407WMNH | Cell 16/17 Area 64C | 31.19 |
| 08/04/04 | 0408WMNH | Cell 16/17 Area 64C | 31.72 |
| 08/04/04 | 0409WMNH | Cell 16/17 Area 64C | 33.85 |
| 08/04/04 | 0410WMNH | Cell 16/17 Area 64C | 27.78 |
| 08/04/04 | 0411WMNH | Cell 16/17 Area 64C | 33.03 |
| 08/04/04 | 0412WMNH | Cell 16/17 Area 64C | 33.66 |
| 08/04/04 | 0413WMNH | Cell 16/17 Area 64C | 32.35 |
| 08/04/04 | 0414WMNH | Cell 16/17 Area 64C | 31.43 |
| 08/04/04 | 0415WMNH | Cell 16/17 Area 64C | 35.11 |
| 08/04/04 | 0416WMNH | Cell 16/17 Area 64C | 32.30 |
| 08/05/04 | 0417WMNH | Cell 16/17 NAPL Building 65 | 28.30 |
| 08/05/04 | 0418WMNH | Cell 16/17 NAPL Building 65 | 27.55 |
| 08/05/04 | 0419WMNH | Cell 16/17 NAPL Building 65 | 31.62 |
| 08/05/04 | 0420WMNH | Cell 16/17 NAPL Building 65 | 31.30 |
| 08/05/04 | 0421WMNH | Cell 16/17 NAPL Building 65 | 31.08 |
| 08/05/04 | 0422WMNH | Cell 16/17 NAPL Building 65 | 31.81 |
| 08/05/04 | 0423WMNH | Cell 16/17 NAPL Building 65 | 31.80 |
| 08/05/04 | 0424WMNH | Cell 16/17 NAPL Building 65 | 32.12 |
| 08/05/04 | 0425WMNH | Cell 16/17 NAPL Building 65 | 31.61 |
| 08/05/04 | 0426WMNH | Cell 16/17 NAPL Building 65 | 33.04 |
| 08/05/04 | 0427WMNH | Cell 16/17 NAPL Building 65 | 32.62 |
| 08/05/04 | 0428WMNH | Cell 16/17 NAPL Building 65 | 32.38 |
| 08/05/04 | 0429WMNH | Cell 16/17 NAPL Building 65 | 31.47 |
| 08/05/04 | 0430WMNH | Cell 16/17 NAPL Building 65 | 31.62 |
| 08/05/04 | 0431WMNH | Cell 16/17 NAPL Building 65 | 32.57 |
| 08/06/04 | 0432WMNH | Cell 16/17 NAPL Building 65 | 31.10 |
| 08/06/04 | 0433WMNH | Cell 16/17 NAPL Building 65 | 29.36 |
| 08/06/04 | 0434WMNH | Cell 16/17 NAPL Building 65 | 29.10 |
| 08/06/04 | 0435WMNH | Building 65 / Area 64C | 28.80 |

| Date Shipped | Doc. Number | Stockpile Area | Net Weight (Tons) (1) |
|----------------------|----------------------|---|-----------------------|
| 08/06/04 | 0436WMNH | Cell 16/17 Area 64C | 30.96 |
| 08/06/04 | 0437WMNH | Cell 16/17 Area 64C | 31.57 |
| 08/06/04 | 0438WMNH | Cell 16/17 Area 64C | 29.02 |
| 08/06/04 | 0439WMNH | Cell 16/17 Area 64C | 29.53 |
| 08/06/04 | 0440WMNH | Cell 16/17 Area 64C | 31.66 |
| 08/06/04 | 0441WMNH | Cell 16/17 Area 64C | 32.54 |
| 08/06/04 | 0442WMNH | Cell 16/17 Area 64C | 30.64 |
| 08/06/04 | 0443WMNH | Cell 16/17 Area 64C | 29.44 |
| 08/06/04 | 0444WMNH | Cell 16/17 Area 64C | 30.35 |
| 08/06/04 | 0445WMNH | Cell 16/17 Area 64C | 30.28 |
| 08/06/04 | 0446WMNH | Cell 16/17 Area 64C | 27.91 |
| 08/09/04 | 0447WMNH | Cell 16/17 NAPL Building 68 | 30.75 |
| 08/09/04 | 0448WMNH | Cell 16/17 NAPL Building 68 | 30.15 |
| 08/09/04 | 0449WMNH | Cell 16/17 NAPL Building 68 | 30.65 |
| 08/09/04 | 0450WMNH | Cell 16/17 NAPL Building 68 | 31.74 |
| 08/09/04 | 0451WMNH | Cell 16/17 NAPL Building 68 | 31.73 |
| 08/09/04 | 0452WMNH | Cell 16/17 NAPL Building 68 | 32.35 |
| 08/09/04 | 0453WMNH | Cell 16/17 NAPL Building 68 Cell 16/17 Area 64C | 34.38 |
| 08/09/04 | 0454WMNH | | 31.91 |
| 08/09/04 08/09/04 | 0455WMNH 0456WMNH | Cell 16/17 Area 64C Cell 16/17 Area 64C | 34.73 35.11 |
| 08/09/04 | 0456WMNH | Cell 16/17 Area 64C | 31.63 |
| 08/09/04 | 0457WMNH | Cell 16/17 Area 64C | 29.77 |
| 08/09/04 | 0459WMNH | Cell 16/17 Area 64C | 34.45 |
| 08/09/04 | 0460WMNH | Cell 16/17 Area 64C | 32.51 |
| 08/09/04 | 0461WMNH | Cell 16/17 Area 64C | 31.79 |
| 08/09/04 | 0462WMNH | Cell 16/17 Area 64C | 32.02 |
| 08/09/04 | 0463WMNH | Cell 16/17 Area 64C | 32.35 |
| 08/09/04 | 0464WMNH | Cell 16/17 Area 64C | 30.67 |
| 08/09/04 | 0465WMNH | Area 64C/D | 30.70 |
| 08/09/04 | 0466WMNH | Cell 18&19 Pretest Area 64D | 34.69 |
| 08/09/04 | 0467WMNH | Cell 18&19 Pretest Area 64D | 33.70 |
| 08/10/04 | 0468WMNH | Cell 18&19 Pretest Area 64D | 28.99 |
| 08/10/04 | 0469WMNH | Cell 18&19 Pretest Area 64D | 32.64 |
| 08/10/04 | 0470WMNH | Cell 18&19 Pretest Area 64D | 32.95 |
| 08/10/04 | 0471WMNH | Cell 18&19 Pretest Area 64D | 31.55 |
| 08/10/04 | 0472WMNH | Cell 18&19 Pretest Area 64D | 28.39 |
| 08/10/04 | 0473WMNH | Cell 18&19 Pretest Area 64D | 34.06 |
| 08/10/04 | 0474WMNH | Cell 18&19 Pretest Area 64D | 22.11 |
| 08/10/04 | 0475WMNH | Cell 18&19 Pretest Area 64D | 32.07 |
| 08/10/04 | 0476WMNH | Cell 18&19 Pretest Area 64D | 31.74 |
| 08/10/04 | 0477WMNH | Cell 18&19 Pretest Area 64D | 32.71 |
| 08/10/04 | 0478WMNH | Cell 18&19 Pretest Area 64D | 30.89 |
| 08/10/04 | 0479WMNH | Cell 18&19 Pretest Area 64D | 33.87 |
| 08/10/04 | 0480WMNH | Cell 18&19 Pretest Area 64D | 30.10 |

| Date Shipped | Doc. Number | Stockpile Area | Net Weight (Tons) (1) |
|----------------------|----------------------|---|-----------------------|
| 08/10/04 | 0481WMNH | Cell 18&19 Pretest Area 64D | 31.26 |
| 08/10/04 | 0482WMNH | Cell 18&19 Pretest Area 64D | 31.36 |
| 08/10/04 | 0483WMNH | Cell 18&19 Pretest Area 64D | 31.10 |
| 08/10/04 | 0484WMNH | Cell 18&19 Pretest Area 64D | 30.96 |
| 08/10/04 | 0485WMNH | Cell 18&19 Pretest Area 64D | 33.19 |
| 08/10/04 | 0486WMNH | Cell 18&19 Pretest Area 64D | 30.85 |
| 08/10/04 | 0487WMNH | Cell 18&19 Pretest Area 64D | 31.95 |
| 08/10/04 | 0488WMNH | Cell 18&19 Pretest Area 64D | 30.32 |
| 08/10/04 | 0489WMNH | Cell 18&19 Pretest Area 64D | 33.96 |
| 08/10/04 | 0490WMNH | Cell 18&19 Pretest Area 64D | 35.60 |
| 08/11/04 | 0491WMNH | Cell 18&19 Pretest Area 64D | 32.48 |
| 08/11/04 | 0492WMNH | Cell 18&19 Pretest Area 64D | 32.02 |
| 08/11/04 | 0493WMNH | Cell 18&19 Pretest Area 64D | 31.60 |
| 08/11/04 | 0494WMNH | Cell 18&19 Pretest Area 64D | 30.58 |
| 08/11/04 | 0495WMNH | Cell 18&19 Pretest Area 64D | 30.14 |
| 08/11/04 | 0496WMNH | Cell 18&19 Pretest Area 64D | 31.04 |
| 08/11/04 | 0497WMNH | Cell 18&19 Pretest Area 64D | 31.86 |
| 08/11/04 | 0498WMNH | Cell 18&19 Pretest Area 64D | 31.09 |
| 08/11/04 | 0499WMNH | Cell 18&19 Pretest Area 64D | 29.70 |
| 08/11/04 | 0500WMNH | Cell 18&19 Pretest Area 64D | 30.46 |
| 08/11/04 08/11/04 | 0501WMNH 0502WMNH | Cell 18&19 Pretest Area 64D Cell 18&19 Pretest Area 64D | 30.62 32.14 |
| 08/11/04 | 0502WMNH | Cell 18&19 Pretest Area 64D | 32.14 |
| 08/11/04 | 0504WMNH | Cell 18&19 Pretest Area 64D | 31.32 |
| 08/11/04 | 0505WMNH | Cell 18&19 Pretest Area 64D | 32.61 |
| 08/11/04 | 0506WMNH | Cell 18&19 Pretest Area 64D | 27.50 |
| 08/11/04 | 0507WMNH | Cell 18&19 Pretest Area 64D | 31.59 |
| 08/11/04 | 0508WMNH | Cell 18&19 Pretest Area 64D | 32.59 |
| 08/11/04 | 0509WMNH | Cell 18&19 Pretest Area 64D | 32.65 |
| 08/11/04 | 0510WMNH | Cell 18&19 Pretest Area 64D | 31.10 |
| 08/11/04 | 0511WMNH | Cell 18&19 Pretest Area 64D | 33.07 |
| 08/11/04 | 0512WMNH | Cell 18&19 Pretest Area 64D | 30.17 |
| 08/11/04 | 0513WMNH | Cell 18&19 Pretest Area 64D | 35.23 |
| 08/12/04 | 0514WMNH | Cell 18&19 Pretest Area 64D | 30.82 |
| 08/12/04 | 0515WMNH | Cell 18&19 Pretest Area 64D | 32.31 |
| 08/12/04 | 0516WMNH | Cell 18&19 Pretest Area 64D | 33.82 |
| 08/12/04 | 0517WMNH | Cell 18&19 Pretest Area 64B | 29.76 |
| 08/12/04 | 0518WMNH | Cell 18&19 Pretest Area 64B | 30.30 |
| 08/12/04 | 0519WMNH | Cell 18&19 Pretest Area 64B | 31.22 |
| 08/12/04 | 0520WMNH | Cell 18&19 Pretest Area 64B | 32.53 |
| 08/12/04 | 0521WMNH | Cell 18&19 Pretest Area 64B | 31.45 |
| 08/12/04 | 0522WMNH | Cell 18&19 Pretest Area 64B | 31.51 |
| 08/12/04 | 0523WMNH | Cell 18&19 Pretest Area 64B | 31.10 |
| 08/12/04 | 0524WMNH | Cell 18&19 Pretest Area 64B | 29.33 |
| 08/13/04 | 0525WMNH | Cell 18&19 Pretest Area 64B | 33.44 |

| Date Shipped | Doc. Number | Stockpile Area | Net Weight (Tons) (1) |
|----------------------|----------------------|---|-----------------------|
| 08/13/04 | 0526WMNH | Cell 18&19 Pretest Area 64B | 31.16 |
| 08/13/04 | 0527WMNH | Cell 18&19 Pretest Area 64B | 29.33 |
| 08/13/04 | 0528WMNH | Cell 18&19 Pretest Area 64B | 31.37 |
| 08/13/04 | 0529WMNH | Cell 18&19 Pretest Area 64B | 30.85 |
| 08/13/04 | 0530WMNH | Cell 18&19 Pretest Area 64B | 26.45 |
| 08/13/04 | 0531WMNH | Cell 18&19 Pretest Area 64B | 27.36 |
| 08/13/04 | 0532WMNH | Cell 18&19 Pretest Area 64B | 28.29 |
| 08/13/04 | 0533WMNH | Cell 18&19 Pretest Area 64B | 28.84 |
| 08/13/04 | 0534WMNH | Cell 18&19 Pretest Area 64B | 29.84 |
| 08/13/04 | 0535WMNH | Cell 18&19 Pretest Area 64B | 28.64 |
| 08/13/04 | 0536WMNH | Cell 18&19 Pretest Area 64B | 30.99 |
| 08/13/04 | 0537WMNH | Cell 18&19 Pretest Area 64B | 30.99 |
| 08/13/04 | 0538WMNH | Cell 18&19 Pretest Area 64B | 28.83 |
| 08/13/04 | 0539WMNH | Cell 18&19 Pretest Area 64B | 31.61 |
| 08/13/04 | 0540WMNH | Cell 18&19 Pretest Area 64B | 25.60 |
| 08/13/04 | 0541WMNH | Cell 18&19 Pretest Area 64B | 26.66 |
| 08/13/04 | 0542WMNH | Cell 18&19 Pretest Area 64B | 30.41 |
| 08/13/04 | 0543WMNH | Cell 18&19 Pretest Area 64B | 32.57 |
| 08/13/04 | 0544WMNH | Cell 16/17 NAPL Building 63 | 27.98 |
| 08/13/04 | 0545WMNH | Cell 16/17 NAPL Building 63 | 32.53 |
| 08/13/04 | 0546WMNH | Cell 16/17 NAPL Building 63 | 30.03 |
| 08/16/04 | 0547WMNH | Cell 16/17 NAPL Building 63 | 32.56 |
| 08/16/04 | 0548WMNH | Cell 16/17 NAPL Building 63 | 29.47 |
| 08/16/04 | 0549WMNH | Cell 16/17 NAPL Building 63 | 30.16 |
| 08/16/04 | 0550WMNH 0551WMNH | Cell 16/17 NAPL Building 63 | 30.28 26.87 |
| 08/16/04 | | Cell 16/17 NAPL Building 63 | |
| 08/16/04 08/16/04 | 0552WMNH 0553WMNH | Cell 16/17 NAPL Building 63 | 30.63 29.14 |
| 08/16/04 | 0554WMNH | Cell 16/17 NAPL Building 63 Cell 16/17 NAPL Building 63 | 30.87 |
| 08/16/04 | 0555WMNH | Cell 16/17 NAPL Building 63 | 33.01 |
| 08/16/04 | 0556WMNH | Cell 16/17 NAPL Building 63 | 30.57 |
| 08/16/04 | 0557WMNH | Cell 16/17 NAPL Building 63 | 32.38 |
| 08/16/04 | 0558WMNH | Cell 16/17 NAPL Building 63 | 32.28 |
| 08/16/04 | 0559WMNH | Cell 16/17 NAPL Building 63 | 30.36 |
| 08/16/04 | 0560WMNH | Cell 16/17 NAPL Building 63 | 29.59 |
| 08/16/04 | 0561WMNH | Cell 16/17 NAPL Building 63 | 32.08 |
| 08/16/04 | 0562WMNH | Cell 16/17 NAPL Building 63 | 29.75 |
| 08/16/04 | 0563WMNH | Cell 16/17 NAPL Building 63 | 29.59 |
| 08/17/04 | 0564WMNH | Cell 16/17 NAPL Building 63 | 28.92 |
| 08/17/04 | 0565WMNH | Cell 16/17 NAPL Building 63 | 29.82 |
| 08/17/04 | 0566WMNH | Cell 16/17 NAPL Building 63 | 31.84 |
| 08/17/04 | 0567WMNH | Cell 16/17 NAPL Building 63 | 33.63 |
| 08/17/04 | 0568WMNH | Cell 16/17 NAPL Building 63 | 32.60 |
| 08/17/04 | 0569WMNH | Cell 16/17 NAPL Building 63 | 30.68 |
| 08/17/04 | 0570WMNH | Cell 16/17 NAPL Building 63 | 34.46 |

| Date Shipped | Doc. Number | Stockpile Area | Net Weight (Tons) (1) |
|--------------|------------------------|-----------------------------|-----------------------|
| 08/17/04 | 0571WMNH | Cell 16/17 NAPL Building 63 | 30.97 |
| 08/17/04 | 0572WMNH | Cell 16/17 NAPL Building 63 | 32.57 |
| 08/17/04 | 0573WMNH | Cell 16/17 NAPL Building 63 | 31.17 |
| 08/18/04 | 0574MWNH | Cell 16/17 NAPL Building 63 | 33.31 |
| 08/18/04 | 0575MWNH | Cell 16/17 NAPL Building 63 | 31.99 |
| 08/18/04 | 0576MWNH | Cell 16/17 NAPL Building 63 | 32.76 |
| 08/19/04 | 0577WMNH | Cell 16/17 NAPL Building 63 | 32.60 |
| 08/19/04 | 0578WMNH | Cell 16/17 NAPL Building 63 | 34.07 |
| 08/19/04 | 0579WMNH | Cell 16/17 NAPL Building 63 | 31.49 |
| | Total of Material Disp | osed | 5,581.13 |

Notes:

(1) Net weights established at the disposal facility

Table 6- NPDES Sampling Results for Water Treatment System August 2004 Monthly Report

GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

(Results are presented in part per billion, ppb)

| Sample ID | Location | Date Collected | Aroclor 1016, 1221, 1232, & 1242 | Aroclor 1248 | Aroclor 1254 | Aroclor 1260 | Total PCBs | Total PCBs Filtered |
|--------------------|----------------------|-------------------|-------------------------------------|--------------|--------------|--------------|------------|------------------------|
| H2-WW000001-0-4G18 | Influent | 18-Aug-04 | ND(0.013) | ND(0.013) | 0.049 | 0.088 | 0.14 | ND(0.013) |
| H2-WW000004-0-4G18 | Modutank Effluent | 18-Aug-04 | ND(0.027) | ND(0.027) | 0.11 | 0.22 | 0.33 | ND(0.013) |
| H2-WW000005-0-4G18 | Sand Filter Effluent | 18-Aug-04 | ND(0.067) | ND(0.067) | 0.46 | 0.19 | 0.65 | 0.026 |
| H2-WW000002-0-4G18 | | 18-Aug-04 | ND(0.013) | ND(0.013) | 0.074 | 0.10 | 0.17 | NS |
| H2-WW000003-0-4G18 | Effluent | 18-Aug-04 | ND(0.013) | ND(0.013) | 0.029 | 0.056 | 0.085 | NS |
| Action Level | Effluent | | 0.50 | 0.50 | 0.50 | 0.50 | 0.50 | N/A |

Notes:

ND(0.013) - Analyte was not detected. The value in parentheses is the associated detection limit.

Modutank Effluent- Sample collected between the modutank and the oil/water separator.

Sand Filter Effluent - Sample collected between the sand and carbon filter.

Intermediate - Sample collected between carbon units which are being operated in series.

NS - Not Sampled

N/A - Not Available

Table 6a - NPDES non-PCB Sampling Results for Water Treatment System August 2004 Monthly Report

GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

(Results are presented in part per billion, ppb)

| Sample ID | H2-WW000001-0-4G18 | H2-WW000004-0-4G18 | H2-WW000005-0-4G18 | H2-WW000002-0-4G18 | H2-WW000003-0-4G18 | NPDES Permi |
|-----------------------------|--------------------|--------------------|----------------------|--------------------|--------------------|-----------------|
| Sample type | Influent | Modutank Effluent | Sand Filter Effluent | Intermediate | Effluent | Regulatory |
| Date Collected | 08/18/2004 | 08/18/2004 | 08/18/2004 | 08/18/2004 | 08/18/2004 | Effluent Limits |
| Analyte | | | | | | |
| APP IX SEMIVOLATILES | | | | | | |
| ACENAPHTHENE | 66.0 | 27.0 | 7.6 J | ND | ND | 100 |
| ACENAPTHYLENE | 2.3 J | 0.96 J | ND | ND | ND | 100 |
| ANTHRACENE | 6.5 J | 2.4 J | ND | ND | ND | 100 |
| BENZO(A)ANTHRACENE | 1.3 J | 1.1 J | ND | ND | ND | 100 |
| BENZO(A)PYRENE | 0.69 J | 0.69 J | ND | ND | ND | 100 |
| BENZO(B)FLUORANTHENE | 0.65 J | 0.76 J | ND | ND | ND | 100 |
| CHRYSENE | 1.3 J | 1.3 J | ND | ND | ND | 100 |
| DI-N-BUTYL PHTHALATE | 0.51 J | ND | ND | ND | ND | 100 |
| FLUORANTHENE | 9.0 J | 7.7 J | ND | ND | ND | 100 |
| FLUORENE | 7.4 J | 2.2 J | ND | ND | ND | 100 |
| PYRENE | 13.0 | 7.7 J | ND | ND | ND | 100 |
| APP IX VOLATILES | | | | | | |
| 1,2,4-TRICHLOROBENZENE | 0.47 J | 0.30 J | ND | ND | ND | 70 |
| ACETONE | 5.0 | 4.6 J | 3.7 J | 2.3 J | ND | 100 |
| CARBON TETRACHLORIDE | ND | ND | ND | 0.34 J | ND | N/A |
| CHLOROFORM | ND | ND | ND | 0.69 J | 0.30 J | 100 |
| CHLOROMETHANE | ND | ND | 0.25 J | ND | ND | N/A |
| CIS-1,2-DICHLOROETHENE | ND | ND | ND | 0.39 J | ND | N/A |
| ETHYL BENZENE | 1.0 | 0.46 J | ND | ND | ND | N/A |
| M,P-XYLENE (SUM OF ISOMERS) | 1.6 | 0.84 J | 0.29 J | ND | ND | * |
| NAPHTHALENE | 1.5 | 0.68 J | 0.24 J | ND | ND | 100 |
| O-XYLENE | 1.1 | 0.59 J | 0.18 J | ND | ND | * |
| TERT-BUTYL METHYL ETHER | 0.30 J | 0.30 J | 0.30 J | 4.4 | 7.2 | 70 |
| TOLUENE | 0.40 J | 0.24 J | ND | ND | ND | * |
| XYLENES (TOTAL) | 2.8 | 1.5 | 0.48 J | ND | ND | * |

Notes:

Modutank Effluent- Sample collected between the modutank and the oil/water separator.

Sand Filter Effluent - Sample collected between the sand and carbon filter.

Intermediate - Sample collected between carbon units which are being operated in series.

Only detected constituents are summarized

ND - not detected

J - Indicates an estimated value

* Total BTEX (Benzene, Toluene, Ethyl Benzene and Xylene) can not exceed 100 ppb

N/A - not available

Table 7 - Daily Air Monitoring Results August 2004 Monthly Report

GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

| Date Collected | Sample Location | Average Site Concentration (mg/m³) | Average Period (Hours:Min) |
|----------------|-----------------|--|-------------------------------|
| | Upwind | 0.120 | 5 |
| | Downwind | | |
| 8/2/2004 | Background | 0.006 | 5 |
| | Upwind | 0.122 | 8 |
| | Downwind | 0.036 | 1 |
| 8/3/2004 | Background | 0.017 | 7 |
| | Upwind | 0.013 | 8 |
| | Downwind | 0.017 | 8 |
| 8/4/2004 | Background | 0.002 | 8 |
| | Upwind | 0.065 | 3 |
| | Downwind | 0.019 | 3 |
| 8/5/2004 | Background | 0.000 | 3 |
| | Upwind | 0.018 | 19 |
| | Downwind | 0.014 | 18 |
| 8/6/2004 | Background | 0.004 | 14 |
| | Upwind | 0.041 | 6 |
| | Downwind | 0.024 | 6 |
| 8/9/2004 | Background | 0.003 | 6 |
| | Upwind | 0.049 | 9 |
| | Downwind | 0.019 | 9 |
| 8/10/2004 | Background | 0.016 | 9 |
| | Upwind | 0.073 | 4 |
| | Downwind | 0.092 | 7 |
| 8/11/2004 | Background | 0.088 | 7 |
| | Upwind | NA | NA |
| | Downwind | NA | NA |
| 8/12/2004 | Background | NA | NA |
| | Upwind | NA | NA |
| | Downwind | NA | NA |
| 8/13/2004 | Background | NA | NA |
| | Upwind | NA | NA |
| | Downwind | NA | NA |
| 8/16/2004 | Background | NA | NA |
| | Upwind | 0.013 | 5 |
| | Downwind | 0.028 | 6 |
| 8/17/2004 | Background | | |
| | Upwind | 0.058 | 4 |
| | Downwind | 0.137 | 4 |
| 8/18/2004 | Background | 0.065 | 4 |

| Date Collected | Sample Location | Average Site Concentration (mg/m³) | Average Period (Hours:Min) |
|--------------------|-----------------|--|-------------------------------|
| | Upwind | NA | NA |
| | Downwind | NA | NA |
| 8/19/2004 | Background | NA | NA |
| | Upwind | 0.041 | 6 |
| | Downwind | 0.087 | 6 |
| 8/20/2004 | Background | 0.042 | 6 |
| | Upwind | 0.011 | 7 |
| | Downwind | 0.045 | 7 |
| 8/23/2004 | Background | 0.003 | 7 |
| | Upwind | 0.038 | 8 |
| | Downwind | 0.002 | 9 |
| 8/24/2004 | Background | 0.000 | 8 |
| | Upwind | 0.012 | 5 |
| | Downwind | 0.051 | 6 |
| 8/25/2004 | Background | 0.006 | 10 |
| | Upwind | 0.008 | 7 |
| | Downwind | 0.044 | 7 |
| 8/26/2004 | Background | 0.004 | 6 |
| | Upwind | 0.038 | 5 |
| | Downwind | 0.075 | 4 |
| 8/27/2004 | Background | 0.040 | 5 |
| | Upwind | NA | NA |
| | Downwind | NA | NA |
| 7/29/2004 | Background | NA | NA |
| | Upwind | NA | NA |
| | Downwind | NA | NA |
| 7/30/2004 | Background | NA | NA |
| notification level | | 0.120 | |
| action level | | 0.150 | |

Notes:

N/A - Not available due to precipitation

Shaded areas indicate readings above the notification level. Engineering controls to reduce the particulates included washing and additional watering of the access roads.

^{--- -} No reading due to technical difficulties with monitoring equipment

Table 8 - Daily Water Column Turbidity Monitoring Results August 2004 Monthly Report

GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

| | Flow at | | Turk | oidity (n | tu) | _ |
|-----------|---------------------|-------------------------------------|---------|-----------|------|-----------------------------|
| Date | Coltsville (cfs) | Location | Average | High | Low | Temperature Average (°C) |
| | | Downstream of Lyman Street Bridge | 15.1 | 40.6 | 8.0 | 22.05 |
| 8/1/2004 | 34 | Downstream of Pomeroy Avenue Bridge | 4.0 | 9.6 | 1.0 | 22.04 |
| | | Downstream of Lyman Street Bridge | 9.7 | 13.6 | 6.0 | 22.43 |
| 8/2/2004 | 46 | Downstream of Pomeroy Avenue Bridge | 88.1 | 802.3 | 1.9 | 22.13 |
| | | Downstream of Lyman Street Bridge | 3.4 | 5.8 | 2.0 | 22.49 |
| 8/3/2004 | 33 | Downstream of Pomeroy Avenue Bridge | 4.4 | 9.2 | 3.2 | 20.98 |
| | | Downstream of Lyman Street Bridge | 8.1 | 16.1 | 4.9 | 22.70 |
| 8/4/2004 | 37 | Downstream of Pomeroy Avenue Bridge | 5.3 | 18.3 | 2.4 | 22.64 |
| | | Downstream of Lyman Street Bridge | 21.8 | 54.2 | 7.9 | 21.23 |
| 8/5/2004 | 65 | Downstream of Pomeroy Avenue Bridge | 7.7 | 20.9 | 2.7 | 21.29 |
| | | Downstream of Lyman Street Bridge | 36.6 | 92.6 | 11.7 | 19.30 |
| 8/6/2004 | 56 | Downstream of Pomeroy Avenue Bridge | 4.9 | 8.8 | 2.1 | 19.27 |
| | | Downstream of Lyman Street Bridge | 73.2 | 167.4 | 19.1 | 17.79 |
| 8/7/2004 | 36 | Downstream of Pomeroy Avenue Bridge | 6.8 | 15.3 | 1.9 | 17.91 |
| | | Downstream of Lyman Street Bridge | 341.0 | 1237.0 | 25.5 | 17.45 |
| 8/8/2004 | 31 | Downstream of Pomeroy Avenue Bridge | 4.1 | 9.0 | 2.6 | 17.47 |
| | | Downstream of Lyman Street Bridge | N/A | N/A | N/A | 17.91 |
| 8/9/2004 | 27 | Downstream of Pomeroy Avenue Bridge | 2.3 | 8.6 | 0.2 | 18.06 |
| | | Downstream of Lyman Street Bridge | N/A | N/A | N/A | 17.91 |
| 8/10/2004 | 26 | Downstream of Pomeroy Avenue Bridge | 2.9 | 6.7 | 0.4 | 19.29 |
| | | Downstream of Lyman Street Bridge | N/A | N/A | N/A | N/A |
| 8/11/2004 | 26 | Downstream of Pomeroy Avenue Bridge | N/A | N/A | N/A | N/A |
| | | Downstream of Lyman Street Bridge | N/A | N/A | N/A | N/A |
| 8/12/2004 | 29 | Downstream of Pomeroy Avenue Bridge | 3.5 | 11.7 | 1.4 | 20.56 |
| | | Downstream of Lyman Street Bridge | N/A | N/A | N/A | N/A |
| 8/13/2004 | 45 | Downstream of Pomeroy Avenue Bridge | 14.2 | 44.4 | 3.1 | 20.11 |
| | | Downstream of Lyman Street Bridge | N/A | N/A | N/A | N/A |
| 8/14/2004 | 69 | Downstream of Pomeroy Avenue Bridge | 9.6 | 20.8 | 4.2 | 20.05 |
| | | Downstream of Lyman Street Bridge | N/A | N/A | N/A | N/A |
| 8/15/2004 | 52 | Downstream of Pomeroy Avenue Bridge | 4.1 | 6.6 | 2.5 | 19.85 |
| | | Downstream of Lyman Street Bridge | N/A | N/A | N/A | N/A |
| 8/16/2004 | 53 | Downstream of Pomeroy Avenue Bridge | 7.3 | 11.5 | 4.6 | 19.14 |
| | | Downstream of Lyman Street Bridge | N/A | N/A | N/A | N/A |
| 8/17/2004 | 71 | Downstream of Pomeroy Avenue Bridge | 5.4 | 9.6 | 2.8 | 18.38 |
| | | Downstream of Lyman Street Bridge | N/A | N/A | N/A | N/A |
| 8/18/2004 | 51 | Downstream of Pomeroy Avenue Bridge | 5.0 | 7.6 | 2.8 | 18.93 |
| | | Downstream of Lyman Street Bridge | 2.7 | 3.0 | 2.3 | 20.36 |
| 8/19/2004 | 39 | Downstream of Pomeroy Avenue Bridge | 3.9 | 7.2 | 2.6 | 19.79 |
| | | Downstream of Lyman Street Bridge | 20.5 | 194.2 | 2.5 | 20.79 |
| 8/20/2004 | 33 | Downstream of Pomeroy Avenue Bridge | 11.4 | 39.8 | 3.0 | 20.64 |

| | Flow at | | Turbidity (ntu) | | | |
|-----------|---------------------|-------------------------------------|-----------------|-------|------|-----------------------------|
| Date | Coltsville (cfs) | Location | Average | High | Low | Temperature Average (°C) |
| | | Downstream of Lyman Street Bridge | 24.3 | 46.7 | 12.0 | 20.13 |
| 8/21/2004 | 324 | Downstream of Pomeroy Avenue Bridge | 58.6 | 380.9 | 12.6 | 20.42 |
| | | Downstream of Lyman Street Bridge | 11.6 | 17.3 | 7.6 | 18.38 |
| 8/22/2004 | 247 | Downstream of Pomeroy Avenue Bridge | 29.0 | 35.3 | 22.9 | 18.35 |
| | | Downstream of Lyman Street Bridge | 2.7 | 3.5 | 2.1 | 18.19 |
| 8/23/2004 | 133 | Downstream of Pomeroy Avenue Bridge | 19.1 | 21.1 | 17.2 | 18.28 |
| | | Downstream of Lyman Street Bridge | 3.6 | 5.9 | 2.8 | 19.59 |
| 8/24/2004 | 82 | Downstream of Pomeroy Avenue Bridge | 18.3 | 20.5 | 15.8 | 19.33 |
| | | Downstream of Lyman Street Bridge | 4.6 | 14.2 | 1.7 | 18.73 |
| 8/25/2004 | 52 | Downstream of Pomeroy Avenue Bridge | 20.2 | 21.7 | 18.9 | 18.46 |
| | | Downstream of Lyman Street Bridge | 3.6 | 5.7 | 2.4 | 18.82 |
| 8/26/2004 | 41 | Downstream of Pomeroy Avenue Bridge | 10.0 | 13.2 | 8.6 | 18.61 |
| | | Downstream of Lyman Street Bridge | 3.4 | 5.3 | 2.3 | 18.85 |
| 8/27/2004 | 35 | Downstream of Pomeroy Avenue Bridge | 7.7 | 24.4 | 3.6 | 19.44 |
| | | Downstream of Lyman Street Bridge | 4.9 | 8.3 | 2.7 | 21.02 |
| 8/28/2004 | 32 | Downstream of Pomeroy Avenue Bridge | 5.5 | 7.1 | 4.0 | 20.72 |
| | | Downstream of Lyman Street Bridge | 5.1 | 9.0 | 2.6 | 22.17 |
| 8/29/2004 | 32 | Downstream of Pomeroy Avenue Bridge | 9.3 | 13.6 | 6.8 | 21.98 |
| | | Downstream of Lyman Street Bridge | 3.5 | 7.6 | 1.4 | 21.29 |
| 8/30/2004 | 31 | Downstream of Pomeroy Avenue Bridge | 60.8 | 138.1 | 8.6 | 23.10 |
| | | Downstream of Lyman Street Bridge | 5.5 | 7.8 | 2.9 | 21.88 |
| 8/31/2004 | 48 | Downstream of Pomeroy Avenue Bridge | 42.1 | 254.9 | 3.4 | 21.89 |

Notes:

Turbidity Action Level - Average Downstream (Pomeroy Avenue)≥ Average Downstream (Lyman Street) + 50 ntu

cfs - Cubic feet per second

ntu - nephelometric turbidity units

Measurements collected using YSI 6200 Data Acquisition System using 600 OMS sonde with a 6136 Turbidity Probe

Flow data was obtained from the USGS Station 01197000 in Coltsville, MA at approximately midday.

Negative values are attributed to +/- 2ntu accuracy of the turbidity probe.

The Lyman Street Turbidity probe will be removed for cleaning and calibration 8/9 through 8/18.

Exceedence on 8/02 is caused by one high reading of 802.3ntu which happened at 6am, construction activities start at 7am therefore the high reading could not have been caused by construction activities. The turbidity avarage for 8/02 without the 802.3 reading is 31.16ntu.

Exceedence on 8/30 due to False readings. The probe was out of the water while both pipes were closed to facilitate pipe relocation.

Data for Pomeroy Avenue location is missing on 8/11 due to an unexplained technical error.

Table 9 - Summary of Turbidity, PCB, and TSS Water Column Monitoring Results August 2004 Monthly Report

GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

| | | | Tu | rbidity | (ntu) | | Calculated | | | | | |
|-----------------------------------|----------|------------|------|---------|---------|-------|------------|------------|--------------------|---------------|---------------|--------|
| | | | | | | Water | Flow | Calculated | | Total PCB | Filtered PCB | |
| | | Estimated | | | Daily | Temp. | Beginning | Flow End | | Concentration | Concentration | TSS |
| Location | Date | Flow (cfs) | High | Low | Average | (°C) | (cfs) | (cfs) | Sample ID | (ug/l) | (ug/l) | (mg/l) |
| Upstream of Newell St. Bridge | 07/22/04 | 45 | NS | NS | NS | NS | NS | NS | H0-SW000054-0-4L22 | ND(0.013) | ND(0.013) | 6.7 |
| Downstream of Lyman St. Bridge | 07/22/04 | 45 | 18.4 | 6.1 | 9.1 | 18.50 | NS | NS | H2-SW000055-0-4L22 | 0.031 | ND(0.013) | 5.0 |
| Downstream of Pomeroy Ave. Bridge | 07/22/04 | 45 | 6.0 | 2.0 | 3.0 | 22.15 | 36.0 | 44.4 | H2-SW000052-0-4L22 | 0.096 | ND(0.013) | 5.1 |
| Upstream of Newell St. Bridge | 08/04/04 | 37 | NS | NS | NS | NS | NS | NS | H0-SW000054-0-4G04 | NS | NS | NS |
| Downstream of Lyman St. Bridge | 08/04/04 | 37 | 16.1 | 4.9 | 8.1 | 22.70 | NS | NS | H2-SW000055-0-4G04 | 0.038 | 0.013 | 6.6 |
| Downstream of Pomeroy Ave. Bridge | 08/04/04 | 37 | 18.3 | 2.4 | 5.3 | 22.64 | 48.1 | 64.4 | H2-SW000052-0-4G04 | 0.088 | 0.019 | 8.8 |
| Downstream of Pomeroy Ave. Bridge | | | | | | | | | | | | |
| (duplicate) | 08/04/04 | 37 | 18.3 | 2.4 | 5.3 | 22.64 | 48.1 | 64.4 | H2-SW000052-1-4G04 | NS | 0.019 | NS |
| Upstream of Newell St. Bridge | 08/19/04 | 39 | NS | NS | NS | NS | NS | NS | H0-SW000054-0-4G19 | ND(0.013) | ND(0.013) | 5.4 |
| Downstream of Lyman St. Bridge | 08/19/04 | 39 | 3.0 | 2.3 | 2.7 | 20.36 | NS | NS | H2-SW000055-0-4G19 | ND(0.013) | ND(0.013) | 4.3 |
| Downstream of Pomeroy Ave. Bridge | 08/19/04 | 39 | 7.2 | 2.6 | 3.9 | 19.79 | 51.7 | 50.8 | H2-SW000052-0-4G19 | 0.039 | ND(0.013) | 7.1 |

Notes:

PCB Action Level - Downstream (Pomeroy Avenue) ≥ Downstream (Lyman Street) + 5 ug/L

ND(0.013) - Analyte was not detected. The value in parentheses is the associated detection limit.

cfs - Cubic feet per second

ntu - nephelometric turbidity units

NS - Not Sampled

Temperature measured YSI 600 oms system.

Flow data was obtained from the USGS Station 01197000 in Coltsville, MA at approximately midday.

Water column samples were collected as 4 grab composite samples.

Two flow values calculated, one at the beginning of the sampling event and one at the end of sampling event.

Table 10 - PCB Air Sampling Results August 2004 Monthly Report

GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

(Results are presented in µg/m³)

| Sample ID | Location (1) | Date Collected | Aroclor 1016, & 1242 | Aroclor 1221, 1232, & 1248 | Aroclor 1254 | Aroclor 1260 | Total PCBs |
|--------------------------------|--------------|----------------|----------------------|-------------------------------|--------------|--------------|-------------|
| H2-AR000007-0-4G12 | background | 12-Aug-04 | ND(0.00261) | ND(0.00261) | 0.00365 | ND(0.00261) | 0.00365 |
| H2-AR000028-0-4G12 | AR000028 | 12-Aug-04 | ND(0.00260) | ND(0.00260) | ND(0.00260) | ND(0.00260) | ND(0.00260) |
| H2-AR000032-0-4G12 | AR000032 | 12-Aug-04 | ND(0.00297) | ND(0.00297) | ND(0.00297) | ND(0.00297) | ND(0.00297) |
| H2-AR000032-1-4G12 (duplicate) | AR000032 | 12-Aug-04 | ND(0.00287) | ND(0.00287) | ND(0.00287) | ND(0.00287) | ND(0.00287) |
| H2-AR000037-0-4G12 | AR000037 | 12-Aug-04 | ND(0.00286) | ND(0.00286) | ND(0.00286) | ND(0.00286) | ND(0.00286) |
| H2-AR000038-0-4G12 | AR000038 | 12-Aug-04 | ND(0.00272) | ND(0.00272) | 0.00272 | ND(0.00272) | 0.00272 |

Notes:

Notification Level: 0.05μg/m³
Action Level: 0.1μg/m³
1- See Figure 1 for locations

Table 11 - Backfill Material Testing Results August 2004 Monthly Report

GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

(Results are presented in part per million, ppm)

| Sample ID | H2-OT000056-0-4L22-1 | H2-OT000056-0-4L22-2 | H2-OT000056-0-4L22-3 | H2-OT000056-0-4L22-4 | H2-OT000056-0-4L22-5 | |
|-----------------------------|----------------------|----------------------|----------------------|----------------------|----------------------|------------|
| Sample type | Common Fill | Regulatory |
| Date Collected | 07/22/2004 | 07/22/2004 | 07/22/2004 | 07/22/2004 | 07/22/2004 | Limits (1) |
| Analyte | | | | | | |
| APP IX SEMIVOLATILES | | | | | | |
| PYRENE | | | | | | 700 |
| APP IX VOLATILES | | | | | | |
| 1,3-DICHLOROBENZENE | | | | | | 100 |
| 2-BUTANONE | | | | | | 0.3 |
| ACETONE | | | | | | 3 |
| ACROLEIN | | | | | | 10 |
| BROMOMETHANE | | | | | | 3 |
| CARBON DISULFIDE | | | | | | 100 |
| DIBROMOMETHANE | | | | | | 500 |
| ETHYL BENZENE | | | | | | 80 |
| M,P-XYLENE (SUM OF ISOMERS) | | | | | | 500 |
| NAPHTHALENE | | | | | | 4 |
| O-XYLENE | | | | | | 500 |
| TETRACHLOROETHYLENE(PCE) | | | | | | 0.5 |
| TOLUENE | | | | | | 90 |
| TRICHLOROETHYLENE (TCE) | | | | | | 0.4 |
| XYLENES (TOTAL) | | | | | | 500 |
| METALS | | | | | | |
| ANTIMONY | | | | | | 10 |
| ARSENIC | | | | | | 30 |
| BARIUM | | | | | | 1000 |
| BERYLLIUM | | | | | | 0.7 |
| CADMIUM | | | | | | 30 |
| CHROMIUM | | | | | | 1000 |
| COBALT | | | | | | 500 |
| COPPER | | | | | | 1000 |
| LEAD | | | | | | 300 |
| MERCURY | | | | | | 20 |
| NICKEL | | | | | | 300 |
| SELENIUM | | | | | | 400 |
| TIN | | | | | | 10 |
| VANADIUM | | | | | | 400 |

| Sample ID | H2-OT000056-0-4L22-1 | H2-OT000056-0-4L22-2 | H2-OT000056-0-4L22-3 | H2-OT000056-0-4L22-4 | H2-OT000056-0-4L22-5 | |
|-----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|------------|
| Sample type | Common Fill | Regulatory |
| Date Collected | 07/22/2004 | 07/22/2004 | 07/22/2004 | 07/22/2004 | 07/22/2004 | Limits (1) |
| Analyte | | | | | | |
| ZINC | | | | | | 2500 |
| PCBS | | | | | | |
| PCB, TOTAL | ND | ND | ND | ND | ND | 0.1* |
| ORGANIC | | | | | | |
| PETROLEUM HYDROCARBON | 43.2 | 33.9 | 34.3 | 36.5 | 34.7 | 200* |

Notes:

Only detected constituents are summarized

ND - not detected

- --- not sampled
- (1) Massachusetts contingency plan S-1 limits
- * Project specific acceptable levels for backfill

Table 11 - Backfill Material Testing Results August 2004 Monthly Report

GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

(Results are presented in part per million, ppm)

| Sample ID | H2-OT000056-0-4L22-6 | H2-OT000165-0-4G11-1 | H2-OT000165-0-4G11-2 | H2-OT000165-0-4G11-3 | H2-OT000165-0-4G11-4 | |
|-----------------------------|----------------------|----------------------|----------------------|----------------------|----------------------|------------|
| Sample type | 07/22/2004 | 08/11/2004 | 08/11/2004 | 08/11/2004 | 08/11/2004 | Regulatory |
| Date Collected | Topsoil | Topsoil | Topsoil | Topsoil | Topsoil | Limits (1) |
| Analyte | | | | | | |
| APP IX SEMIVOLATILES | | | | | | |
| PYRENE | ND | .026 J | | | | 700 |
| APP IX VOLATILES | | | | | | |
| 1,3-DICHLOROBENZENE | .00097 J | ND | | | | 100 |
| 2-BUTANONE | .0096 | .0056 J | | | | 0.3 |
| ACETONE | .082 | .051 | | | | 3 |
| ACROLEIN | ND | .0047 J | | | | 10 |
| BROMOMETHANE | .0012 J | ND | | | | 3 |
| CARBON DISULFIDE | .00099 J | ND | | | | 100 |
| DIBROMOMETHANE | .0018 J | ND | | | | 500 |
| ETHYL BENZENE | .00095 J | ND | | | | 80 |
| M,P-XYLENE (SUM OF ISOMERS) | .0024 J | ND | | | | 500 |
| NAPHTHALENE | .0044 J | ND | | | | 4 |
| O-XYLENE | .0014 J | ND | | | | 500 |
| TETRACHLOROETHYLENE(PCE) | .0047 J | ND | | | | 0.5 |
| TOLUENE | .0065 | .0015 J | | | | 90 |
| TRICHLOROETHYLENE (TCE) | .003 J | ND | | | | 0.4 |
| XYLENES (TOTAL) | .0038 J | ND | | | | 500 |
| METALS | | | | | | |
| ANTIMONY | 0.41 | 0.85 | | | | 10 |
| ARSENIC | 2.7 | 5.1 | | | | 30 |
| BARIUM | 12.4 | 35.7 | | | | 1000 |
| BERYLLIUM | 0.22 | 0.35 | | | | 0.7 |
| CADMIUM | 0.20 | 0.40 | | | | 30 |
| CHROMIUM | 3.5 | 9.3 | | | | 1000 |
| COBALT | 4.0 | 7.3 | | | | 500 |
| COPPER | 7.2 | 12.6 | | | | 1000 |
| LEAD | 3.7 | 12.8 | | | | 300 |
| MERCURY | ND | 0.057 | | | | 20 |
| NICKEL | 7.1 | 12.1 | | | | 300 |
| SELENIUM | ND | 1.1 | | | | 400 |
| TIN | ND | 1.0 | | | | 10 |
| VANADIUM | 4.2 | 11.3 | | | | 400 |
| | | | | | | |

| Sample ID | H2-OT000056-0-4L22-6 | H2-OT000165-0-4G11-1 | H2-OT000165-0-4G11-2 | H2-OT000165-0-4G11-3 | H2-OT000165-0-4G11-4 | |
|-----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|------------|
| Sample type | 07/22/2004 | 08/11/2004 | 08/11/2004 | 08/11/2004 | 08/11/2004 | Regulatory |
| Date Collected | Topsoil | Topsoil | Topsoil | Topsoil | Topsoil | Limits (1) |
| Analyte | | | | | | |
| ZINC | 25.9 | 56.8 | | | | 2500 |
| PCBS | | | | | | |
| PCB, TOTAL | ND | ND | ND | ND | ND | 0.1* |
| ORGANIC | | | | | | |
| PETROLEUM HYDROCARBON | 30.1 | 92.2 | 53.6 | 48.2 | 90.1 | 200* |

Notes:

Only detected constituents are summarized

ND - not detected

--- not sampled

(1) - Massachusetts contingency plan S-1 limits

* - Project specific acceptable levels for backfill

Table 12 - Cell 18E/19E NAPL-Impacted Material Characterization Analytical Results August 2004 Monthly Report GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

(Results are presented in part per million, ppm)

| Sample ID | H2-OT000166-0-4G16 | H2-OT000167-0-4G16 | H2-OT000168-0-4G16 | H2-OT000172-0-4G26 A | H2-OT000172-0-4G26 B |
|-----------------------------|--------------------|--------------------|--------------------|-----------------------------|-----------------------------|
| | stockpile material | stockpile material | stockpile material | stockpile material | stockpile material |
| Sample type | characterization | characterization | characterization | characterization | characterization |
| Date Collected | 08/16/2004 | 08/16/2004 | 08/16/2004 | 08/26/2004 | 08/26/2004 |
| Stockpile Location | Building 68 | Building 68 | Building 68 | Building 68 | Building 68 |
| Analyte | | | | | |
| PCB, TOTAL | 12 | 2.5 | 5 | 5.2 | 4.1 |
| AROCLOR-1254 | 2.9 | .73 | 1.7 | 1.2 | 0.68 |
| AROCLOR-1260 | 8.6 | 1.8 | 3.3 | 4.0 | 3.4 |
| APP IX SEMIVOLATILES | | • | | | |
| 2-METHYLNAPHTHALENE | 74 | 220 | 51 | | |
| 4-METHYLPHENOL | .48 J | 1.4 J | ND | | |
| ACENAPHTHENE | 52 | 220 | 78 | | |
| ACENAPTHYLENE | 24 | 11 | 3.6 J | | |
| ACETOPHENONE | .25 J | ND | ND | | |
| ANTHRACENE | 62 | 190 | 51 | | |
| BENZO(A)ANTHRACENE | 46 | 120 | 36 | | |
| BENZO(A)PYRENE | 37 | 97 | 29 | | |
| BENZO(B)FLUORANTHENE | 27 | 53 J | 21 | | |
| BENZO(GHI)PERYLENE | 12 J | 35 J | 11 J | | |
| BENZO(K)FLUORANTHENE | 31 | 76 J | 21 | | |
| CHRYSENE | 41 | 110 | 32 | | |
| DIBENZO(A,H)ANTHRACENE | 5.1 J | 12 J | 3.7 J | | |
| DIBENZOFURAN | 25 J | 52 J | 9.4 J | | |
| FLUORANTHENE | 94 | 270 | 72 | | |
| FLUORENE | 55 | 140 | 40 | | |
| INDENO(1,2,3-C,D)PYRENE | 13 J | 36 J | 9.7 J | | |
| NAPHTHALENE | 72 | 400 | 45 | | |
| PHENANTHRENE | 180 | 520 | 140 | | |
| PYRENE (mg/kg) | 100 | 280 | 95 | | |
| APP IX VOLATILES | | | | | |
| 1,2,4-TRICHLOROBENZENE | ND | 9 J | ND | | |
| 1,4-DIOXANE (P-DIOXANE) | ND | 3300 | ND | | |
| ACETONE | ND | ND | 5.7 | | |
| ETHYL BENZENE | ND | 48 | 4.9 | | |
| M,P-XYLENE (SUM OF ISOMERS) | .68 J | 37 | 3.4 | | |
| NAPHTHALENE | 80 | 700 | 98 | | |
| O-XYLENE | ND | 15 J | 2 J | | |
| XYLENES (TOTAL) | .7 J | 54 | 5.5 | | |
| INORGANICS | T = - | T . | | | T |
| CORROSIVITY BY PH (ph) | 7.8 | 7.4 | 7.6 | | |
| IGNITABILITY (deg f) | >150 | >150 | >150 | | |
| PAINT FILTER LIQUIDS (ml) | ABSENT | ABSENT | ABSENT | | |

| Sample ID | H2-OT000166-0-4G16 | H2-OT000167-0-4G16 | H2-OT000168-0-4G16 | H2-OT000172-0-4G26 A | H2-OT000172-0-4G26 B |
|--------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|
| Sample type | stockpile material characterization |
| Date Collected | 08/16/2004 | 08/16/2004 | 08/16/2004 | 08/26/2004 | 08/26/2004 |
| Stockpile Location | Building 68 |
| Analyte | | | | | |
| PERCENT SOLIDS (%) | 81.3 | 75.7 | 80.8 | 85.6 | 83.2 |
| SULFIDE (mg/kg) | ND | ND | ND | | |
| CYANIDE (mg/kg) | ND | 0.75 | ND | | |
| TCLP HERBICIDES | | | | | |
| | all Non-Detects | all Non-Detects | all Non-Detects | | |
| TCLP METALS | | | | | |
| ARSENIC, TCLP LEACHATE (mg/l) | ND | .0037 | ND | | |
| BARIUM, TCLP LEACHATE (mg/l) | .448 | .693 | .473 | | |
| CADMIUM, TCLP LEACHATE (mg/l) | .00077 | .0033 | ND | | |
| CHROMIUM, TCLP LEACHATE (mg/l) | .0024 | .0059 | .0015 | | |
| LEAD, TCLP (mg/l) | .0376 | .152 | .0093 | | |
| SELENIUM, TCLP LEACHATE (mg/l) | .0139 | .0121 | .0086 | | |
| TCLP PESTICIDES | | | | | |
| | all Non-Detects | all Non-Detects | all Non-Detects | | |
| TCLP SEMIVOLATILES | • | • | | | |
| | all Non-Detects | all Non-Detects | all Non-Detects | | |
| TCLP VOLATILES | • | • | | | |
| | all Non-Detects | all Non-Detects | all Non-Detects | | |
| Matan | | | · | • | • |

Notes:

Only detected constituents are summarized

ND - not detected

--- - not sampled

Table 13 - Cell 19E, Excavation Confirmation Samples Analytical Results August 2004 Monthly Report GE-Pittsfield/Housatonic River Project 1.5 Mile Removal Action Pittsfield, MA

(Results are presented in part per million, ppm)

| Sample ID | H2-OT000169-0-4G24 | H2-OT000170-0-4G24 | H2-OT000171-0-4G24 |
|--------------------|--------------------|--------------------|--------------------|
| Sample type | Cell 19E sediment | Cell 19E sediment | Cell 19E sediment |
| Date Collected | 08/24/2004 | 08/24/2004 | 08/24/2004 |
| Analyte | | | |
| PCBS | | | |
| AROCLOR-1254 | 0.16 | ND | ND |
| AROCLOR-1260 | 0.77 | ND | ND |
| PCB, TOTAL | 0.93 | ND | ND |
| INORGANICS | | | |
| PERCENT SOLIDS (%) | 86.3 | 86.1 | 86.2 |

Notes

Only detected constituents are summarized

ND - not detected



Photograph 1 – Cell 18E, Excavation Activities



Photograph 2 – High Pressure Washing/Vacuuming of Bedrock in Cell 18E



Photograph 3– Installation of Common Fill in Cell 18E



Photograph 4– Installation of Filter Stone in Cell 18E



Photograph 5– Cell 18E Restored



Photograph 6 - Gabion Basket Removal in Cell 18W

